



Log No. K82-132
File: RR 2 (NP-33-81-37)

January 25, 1982

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Administrator, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137



Dear Mr. Keppler:

Enclosed are three copies of Licensee Event Report 81-031, including supplemental information sheets, which have been revised. The revisions to the report are indicated by a "5" in the left margin of each page.

Please replace your previous copies of this report with the attached revision.

Yours truly,

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Richard Deyoung, Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Luis Reyes
NRC Resident Inspector
Encl: 1 copy

8202020476 820125
PDR ADOCK 05000346
S PDR

THE TOLEDO EDISON COMPANY PLAZA 300 MADISON AVENUE TOLEDO, OHIO 43652

JAN 28 1982

IE22
5
11