




ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

January 25, 1982

2CAN018205

Mr. G. L. Madsen, Chief
Reactor Project Branch
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Licensee Event Report
No. 81-034/99X-1
(File: 2-0520)



Gentlemen:

Attached is an informational report concerning internal damage discovered in two valves (2MS-39A and 2MS-39B) during Mode 5 operation. This an update to a previous submittal dated 10/13/81.

Very truly yours,

John R. Marshall
Manager, Licensing

JRM:GAC:s1

Attachment

cc: Mr. Richard C. DeYoung
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Norman M. Haller, Director
Office of Management & Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE 22
S
1/1