Carolina Power & Light Company NRC REGION TO

January 20, 1982

82 JAN 25 A 5 : 60AD 82-105

File: SH N-2/18 Item 66

Mr. James P. O'Reilly United States Nuclear Regulatory Commission Region II 10: Marietta Street, Northwest Atlanta, Georgia 30303

> SHEARON HARRIS NUCLEAR POWER PLANT DOCKET NOS. 50-400, 50-401 INSUFFICIENT FILLET WELD LENGTH ON UNITS 1 AND 2 SEISMIC I CABLE TRAY AND HVAC HANGERS

Dear Mr. O'Reilly:

On December 22, 1981, the NRC (Mr. C. Julian) was informed that the subject item was considered potentially reportable per the provisions of 10CFR50.55(e). The intent of this letter is to inform you that, due to the extent of this problem, we have not been able to complete our reportability evaluation on this matter. It is anticipated that the field investigation of this problem will be completed by April 1, 1982, and the reportability evaluation will be completed by May 1, 1982, at which time the NRC will be informed of the results of our evaluation.

Thank you for your consideration in this matter.

KVH/gea

Yours very truly

cc: Mr. G. Maxwell Mr. V. Stello (2)

> N. J. Chiangi - Manager Engineering & Construction Quality Assurance/Quality Control

202100312 8201 PDR ADOCK 05000400

