TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

82 FEB 2 A8: 47

January 29, 1982

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE REPORT BFRO-50-260/81069

The enclosed report provides details concerning scram discharge level switch 2-LS-85-45E (25-gallon rod block) which was found to be inoperable. This report is submitted in accordance with NRC Bulletin 80-14.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

Records Center Institute of Nuclear Power Operations 1820 Water Place Atlanta, Georgia 30339

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

CEPHCIAL CUPIL)

IE 22:/