

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401 REGION II
1750 Chestnut Street Tower II ATLANTA, GEORGIA

February 1, 1982

82 FEB 2 A8.40

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE
REPORT BFRO-50-259/82002

The enclosed report provides details concerning drywell high pressure
switch 1-PS-64-58C which was found to be isolated. This report is
submitted in accordance with Browns Ferry unit 1 Technical Specification
6.7.2.b.2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Green
A. J. Green
Director of Nuclear Power



Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

OFFICIAL COPY

IE 22
5/11

8202160258 820201
PDR ADOCK 05000259
S PDR

An Equal Opportunity Employer