



Log No. K82-216
File: RR 2 (NP-33-82-04)

February 5, 1982

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Administrator, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137



Dear Mr. Keppler:

Reportable Occurrence 82-003
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: January 8, 1982

Enclosed are three copies of Licensee Event Report 82-003 with a supplemental information sheet which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D Murray

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Information and Program Analysis
Encl: 3 copies

Mr. Luis Reyes
NRC Resident Inspector
Encl: 1 copy

8202160303 820205
PDR ADDCK 05000346
S PDR

IE22
3/11