

APPENDIX A

NOTICE OF VIOLATION

Duquesne Light Company
Beaver Valley Power Station, Unit 1

Docket No. 50-334
License No. DPR-66

As a result of the inspection conducted on November 24, 1981 - January 4, 1982, and in accordance with the Interim Enforcement Policy, 45FR66754 (October 7, 1980), the following violation was identified:

Technical Specification 6.8.1.a requires implementation of written procedures as recommended in Appendix A of Regulatory Guide 1.33, November 1972. Regulatory Guide 1.33, Appendix A, Item E, recommends procedures for Correcting Abnormal, Off-normal, or Alarm Conditions. The BVPS Operating Manual, Section 1.11.4.K, Correcting Safety Related Alarm Conditions - Boron Injection Surge Tank Level Low, Issue 2, Revision 7, requires chemical sampling prior to adding makeup water after a low level alarm.

Contrary to the above, on November 24, 1981, no sample was taken prior to adding makeup water after a surge tank low level alarm.

This is a Severity Level V Violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Duquesne Light Company is hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation. Where good cause is shown, consideration will be given to extending your response time.

Date JAN 29 1982

Original Signed by
R. R. Keimig for
Richard W. Starostecki, Director
Division of Resident and Project
Inspection

OFFICE							
SURNAME							
DATE	8202160465	820129					
	PDR ADOCK	05000334					
	G	PDR					