	LICENSEE EVENT REPORT
	CONTROL BLOCK: [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N J S G S 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 B LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
O 1 8	REPORT L 6 0 5 0 0 0 3 1 1 7 0 1 1 0 8 2 8 0 2 0 8 3 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	On January 10, 1982 the operator noticed that the No. 24 Steam Generator Pressure
0 3	Channel 4 had failed high. At 0300 hours the pressure channel was declared inoperable
0 4	and Action Statement 3.3.2 Action 14 was entered.
0 5	
06	
0 7	
08	9 80
0 9	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
	17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE COMPONENT NETHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER X 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 N 25 Z 9 9 9 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0	The reason No. 24 Steam Generator Pressure Channel 4 failed high was the ventilation
1 1	damper stuck open, freezing the pressure sensing line. The ventilation damper was
1 2	freed and exercised, then closed. The pressure sensing line was thawed, tested, and
13	returned to service. At 0325 hours, January 10, 1982, Action Statement 3.3.2 Action
7 8	14 was terminated.
1 5	FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 DISCOVERY DISCOVERY DESCRIPTION 32 DISCOVERY DE
1 6 8	CCTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 Z 33 Z 34 NA 9 10 11 44 45 NA 80
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 1 1 12 13 NA 80
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION
7 8	PUBLICITY ISSUED DESCRIPTION 45 PDR ADOCK 05000311 NRC USE ONLY
2 0	ISSUED DESCRIPTION (45) NAC. USE ONLY PDR ADOCK PDR ADOCK S 68 69 80 80 8
	NAME OF PREPARER Frank Dickey PHONE: 609-935-0998