

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | J | S | G | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 14 15 25 26 30 57 58

CON'T
0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 7 | 2 | 7 | 0 | 1 | 1 | 3 | 8 | 2 | 8 | 0 | 2 | 1 | 0 | 8 | 2 | 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On January 13, 1982, an operator discovered that the Air Particulate Detector (APD)
0 3 | Pump had failed. An attempt to restart it was unsuccessful. Therefore, at 0001
0 4 | hours, the APD Pump was declared inoperable, rendering radiation monitor 1R11A,
0 5 | 1R12A, and 1R12B inoperable, and Action Statements 3.3.3.1.b Action 22 and 3.9.9.
0 6 | were entered.
0 7 |
0 8 |

0 9 | SYSTEM CODE | M | C | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | B | 13 | COMPONENT CODE | I | N | S | T | R | U | 14 | COMP. SUBCODE | E | 15 | VALVE SUBCODE | Z | 16 |
7 8 9 10 11 12 13 18 19 20
17 | LER RO REPORT NUMBER | 8 | 2 | 21 | 22 | SEQUENTIAL REPORT NO. | 0 | 0 | 6 | 24 | 26 | OCCURRENCE CODE | / | 27 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32 |
ACTION TAKEN | A | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 37 | 40 | ATTACHMENT SUBMITTED | Y | 23 | NPRD-4 FORM SUB. | Y | 24 | PRIME COMP. SUPPLIER | L | 25 | COMPONENT MANUFACTURER | L | 1 | 8 | 5 | 26 | 44 | 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | All of the required containment purge and pressure-vacuum relief penetrations were
1 1 | isolated. The high speed and low speed filter paper drives were replaced and the
1 2 | APD was tested satisfactorily. At 0030 hours, January 14, 1982, Action Statements
1 3 | 3.3.3.1.b Action 22 and 3.9.9 were terminated.
1 4 |

1 5 | FACILITY STATUS | H | 28 | % POWER | 0 | 0 | 0 | 29 | OTHER STATUS | N/A | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | Operator Observation | 32 |
7 8 9 10 12 13 44 45 46 80

1 6 | ACTIVITY CONTENT RELEASED OF RELEASE | Z | 33 | Z | 34 | AMOUNT OF ACTIVITY | N/A | 35 | LOCATION OF RELEASE | N/A | 36 |
7 8 9 10 11 44 45 80

1 7 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | N/A | 39 |
7 8 9 11 12 13 80

1 8 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | N/A | 41 |
7 8 9 11 12 80

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | N/A | 43 |
7 8 9 10 80

2 0 | PUBLICITY ISSUED DESCRIPTION | N | 44 | DESCRIPTION | N/A | 45 | NRC USE ONLY
7 8 9 10 68 69 80

Frank Dickey

PHONE: 609-935-0998

8202220422 820210
PDR ADOCK 05000272
S PDR

540 917-928