

MAGNA ✓ CHEK

2125 RIGGS STREET
WARREN, MICHIGAN 48091

February 11, 1982

(313) 756-4070

United States Nuclear Regulatory Comm.
Region III
799 Roosevelt Rd
Glen Ellyn, Illinois 60137

Reference: License #21-19111-01

Gentlemen:

In reply to your letter dated Dec 22, 1981, regarding the routine safety inspection performed on Nov 18, 1981. The three conditions of non-compliance mentioned in said letter were corrected in the following manner:


1) License condition #19 and page 25 of our Administration Manual states that unannounced on the job inspections at intervals not to exceed three months will be performed by the R.S.O. This was not accomplished during the past two quarters because we had little work in the field during that period of time and the R.S.O. was utilized as a Radiographer in the field for the few jobs that we performed.

2) 10 CFR 34.43(c) requiring that a record be kept for two years per 10 CFR 34.43 (b) of the last survey prior to locking the exposure device and ending direct surveillance of the operation. Apparently, we misinterpreted this section. We were of the opinion that this meant the survey upon securing the device in the storage vault as recorded on our Radiographic Utilization Log, line 9C, (survey meter reading at the time of return to storage). To correct this error, we are now recording in this space the readings after the last exposure at the surface of the exposure device. We have all records generated by our radiographic operations dating back to the time we took possession of our first source and will maintain these records for at least the specified two year period.

3) 10 CFR 20.407(d) requiring the calendar year exposure report. Please find enclosed said report from the years 1980 & 1981. Yearly exposure reports will be forthcoming on a timely basis in the future.

Sincerely,

8203160496 820308
NMS LIC30
21-19111-01 PDR


Lawrence E. Jones
President

MAR 2 1982

LEJ/ap

I, Lawrence E. Jones, do hereby affirm that all of the above statements

MAGNA ✓ CHEK TM ✓

2125 RIGGS STREET
WARREN, MICHIGAN 48091

February 11, 1982

(313) 756-4070

United States Nuclear Regulatory Comm.
Region III
799 Roosevelt Rd
Glen Ellyn, Illinois 60137



Reference: License #21-19111-01

Gentlemen:

In reply to your letter dated Dec 22, 1981, regarding the routine safety inspection performed on Nov 18, 1981. The three conditions of non-compliance mentioned in said letter were corrected in the following manner:

- 1) License condition #19 and page 25 of our Administration Manual states that unannounced on the job inspections at intervals not to exceed three months will be performed by the R.S.O. This was not accomplished during the past two quarters because we had little work in the field during that period of time and the R.S.O. was utilized as a Radiographer in the field for the few jobs that we performed.
- 2) 10 CFR 34.43(c) requiring that a record be kept for two years per 10 CFR 34.43 (b) of the last survey prior to locking the exposure device and ending direct surveillance of the operation. Apparently, we misinterpreted this section. We were of the opinion that this meant the survey upon securing the device in the storage vault as recorded on our Radiographic Utilization Log, line 9C, (survey meter reading at the time of return to storage). To correct this error, we are now recording in this space the readings after the last exposure at the surface of the exposure device. We have all records generated by our radiographic operations dating back to the time we took possession of our first source and will maintain these records for at least the specified two year period.
- 3) 10 CFR 20.407(d) requiring the calendar year exposure report. Please find enclosed said report from the years 1980 & 1981. Yearly exposure reports will be forthcoming on a timely basis in the future.

Sincerely,



Lawrence E. Jones
President

ACCOUNT NO.	SERIES CODE
64321	

MI 48041

RADIATION
DOSIMETRY
REPORT

R. S. Landauer, Jr. & Co.

Division of Technical Operations, Incorporated

Glenwood Science Park
Glenwood, Illinois 60425
Telephone (312) 755-7000



REPORTING PERIOD	PROCESS NO.	FINISHING DATE	QUARTERLY SUMMARY PLAN #	NO. CAP.	NO. LVS.	NO. OF PAGES
JUNE WEEK	10210	11501	1 CAL. QUARTER TO DATE 2 NO SUMMARY 3 ONE 2 AND 1 ABOVE	1	95999	1

[illegible][illegible]

ACCOUNT NO	04321
SERIAL CODE	

11541

RADIATION DOSIMETRY REPORT

R. S. Landauer, Jr. & Co.
Division of Tech/Ops, Inc.

Glenwood Science Park
Glenwood, Illinois 60425
Telephone (312) 755-7000

Tech/Ops

Londoner

EXPOSURE PERIOD	PROCESS NO.	PRODUCTION LOT	QUANTITY SUMMARY PLAS.	NET CUP	OVER LIT	NET/PLAS NO.
7-10-53 A	13447	1-2402	2 CAL. QUARTER TO DATE 1 NO SUMMARY 5 NET, 1 AND 1 ABOVE	1	9-999	CI 1

[illegible]