

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | P | A | B | V | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5

7 8 9 14 15 25 26 30 37 38
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CVT
01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 3 | 4 | 7 | 0 | 2 | 0 | 5 | 8 | 2 | 8 | 0 | 3 | 0 | 4 | 8 | 2 | 9

7 8 60 61 68 69 74 75 80
REPORT SOURCE DCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 | At 1130 hours on 2/5/82 a fire barrier penetration between the west

03 | cable vault and auxiliary feed pump area was found unattended without

04 | a fire retardant seal in place. A fire watch was immediately

05 | reestablished in compliance with Technical Specification 3.7.1.5.

06 | This has been a repetitive incident involving construction personnel.

07 | _____

08 | _____

09 | _____

7 8 9
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
03 | A | B | 11 | D | 12 | Z | 13 | Z | Z | Z | Z | Z | Z | 14 | Z | 15 | Z | 16

17 LER NO. REPORT NUMBER | EVENT YEAR | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE | REVISION NO.
82 | _____ | 005 | / | 03 | I | 0

ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER
B18 | G19 | Z20 | Z21 | 0000 | Y23 | N24 | Z25 | Z999926

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 | In August, 1981, a construction department maintenance procedure change

11 | was made addressing the need for sealing opened penetrations at the

12 | end of the shift. The procedure will be revised to address the

13 | specific technical specification requirements and reviewed by the

14 | DLC Fire and Safety Engineer for compliance with Tech. Spec. 3.7.1.5.

1 FACILITY STATUS | % POWER | OTHER STATUS | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION
15 | G28 | 000029 | Design Modifica- | A31 | Observation

2 ACTIVITY CONTENT | AMOUNT OF ACTIVITY | LOCATION OF RELEASE
16 | Z33 | Z34 | N/A | _____ | N/A36

3 PERSONNEL EXPOSURES | PERSONNEL INJURIES
NUMBER | TYPE | DESCRIPTION | NUMBER | DESCRIPTION
17 | 000037 | Z38 | N/A | 000040 | N/A41

4 LOSS OF OR DAMAGE TO FACILITY | PUBLICITY
TYPE | DESCRIPTION | NUMBER | DESCRIPTION
18 | Z42 | N/A43 | N44 | N/A45

8203170388 820304
PDR ADDCK 05000334
S PDR

NRC USE ONLY

NAME OF PREPARED BY: **W. S. Lacey**

PHONE: **412-643-8525**

80
7-225
00

Attachment to LER 82-005/03L
Beaver Valley Power Station
Duquesne Light Company
Docket No. 50-334

No further information is available or needed to satisfy the reporting requirement.