



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

March 12, 1982

Regional Administrator-III
US Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137



MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Reactor Water Cleanup Inboard Containment Isolation
Valve Failure Due to Electrical Short

The Licensee Event Report for this occurrence is attached.

This event is reported in compliance with Technical Specification 6.7.B.2.b since it represents operation in a degraded mode permitted by a limiting condition for operation.

Kevin H. Carley for

L O Mayer, PE
Manager of Nuclear Support Services

LOM/KNC/bp

Attachment

cc NRC Document Control Desk (1)
NRC Resident Inspector
MPCA
Attn J W Ferman

8203230403 820312
PDR ADOCK 05000263
S PDR

IE22
5/1
MAR 15 1982