

APPENDIX A
NOTICE OF VIOLATION

Florida Power Corporation
Crystal River

Docket No. 50-302
License No. DPR-72

As a result of the inspection conducted on November 17-20, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified.

Technical Specification 3.7.12 requires all penetration fire barriers protecting safety related areas to be functional at all times. With one or more of the penetration fire barriers nonfunctional, a continuous fire watch is required to be established on at least one side of the affected penetration within one hour. Fire doors in fire barriers are penetration fire barriers and must be maintained functional or a fire watch established.

Contrary to the above, the fire door for the fire barrier penetration between the hot machine shop and the 119 foot elevation of the auxiliary building was found on November 17, 1981 to be nonfunctional and a fire watch had not been established. This door was found blocked and wedged in the open position due to inoperative door closers and latching hardware.

This is a Severity Level V Violation (Supplement I.E). A similar item was previously identified by NRC Report 302/81-1.

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation.

Date: DEC 08 1981