



Log No. K82-513
File: RR 2 (NP-33-82-12)

March 18, 1982

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:



Reportable Occurrence 82-010
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: February 19, 1982

Enclosed are three copies of Licensee Event Report 82-010 with supplemental information sheets which are being provided in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D Murray /smq

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Luis Reyes
NRC Resident Inspector
Encl: 1 copy

IEER
5/1