MERÍDIA HURON HOSPITAL

May 990

United states Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137 Liceme 7 ile 34-01505-01 30-2750

Re: License No. 34-01505-01

Attn: D. J. Sreniawski, Chief

Per your request, the following is additional information regarding the regional inspection by your office on January 9, 1990 for Meridia Huron Hospital.

The following items are submitted as you requested:

As of January 10, 1990, the following items have been in full compliance:

- 1. Surveys will be performed in accordance with 10 CFR 30 .70 (a), at the end of each day of use where radicpharmaceuticals are prepared or administered. This item was reviewed with Nuclear Medicine personnel indicating that these records will be reviewed periodically by our Consulting Physicist to avoid any further violation.
- 2. In accordance with 10 CFR 35 .50 (b) (3), quarterly linearities are being performed on the dose calibrator. This violation was reviewed with Nuclear Medicine personnel with full compliance being required as of January 9, 1990. The activity linearity evaluations will be reviewed by our Consulting Physicist and also reviewed at the Radiation Safety Committee meeting.
- 3. As of January 9, 1990, any authorized users listed on NRC license No. 34-01505-01 will use by-product materials. All of the work being done in the Research Center will be read by A. Rejali, M.D.

Should you have any further questions, please do not hesitate to contact me.

Sincerel

Vice Presi

Operations

13951 Terrace Road Cleveland, Ohio 44112 (216) 761-3300 TE 07