

Georgia Power Company
40 Inverness Center Parkway
Post Office Box 1295
Birmingham, Alabama 35201
Telephone 205 877-7279

J. T. Beckham, Jr.
Vice President - Nuclear
Hatch Project



May 14, 1993

Docket No. 50-321

HL-3292
005419


U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Edwin I. Hatch Nuclear Plant - Unit 1
Licensee Event Report
Blown Fuse Results in Unplanned Automatic
Actuations of Engineered Safety Features

Gentlemen:

In accordance with the requirements of 10 CFR 50.73(a)(2)(iv), Georgia Power Company is submitting the enclosed Licensee Event Report (LER) concerning a blown fuse which caused unplanned automatic actuations of engineered safety features. This event occurred at Plant Hatch - Unit 1.

Sincerely,


J. T. Beckham, Jr.

MCM/cr

Enclosure: LER 50-321/1993-005

cc: Georgia Power Company
Mr. H. L. Sumner, General Manager - Nuclear Plant
NORMS

U.S. Nuclear Regulatory Commission, Washington, D.C.
Mr. K. Jabbour, Licensing Project Manager - Hatch

U.S. Nuclear Regulatory Commission, Region II
Mr. S. D. Ebnetter, Regional Administrator
Mr. L. D. Wert, Senior Resident Inspector - Hatch

180033
9305190378 930514
PDR ADDCK 05000321
S PDR

JEJ