



STANDARD
Reuter-Stokes

Reuter-Stokes, Inc.
Edison Park
8489 Darrow Road, Twinsburg, Ohio 44067-2398
216 425-4755 Fx 425-4045

June 14, 1993

B.J. Holt, Chief
Nuclear Materials Inspection Section I
US Nuclear Regulatory Commission
799 Roosevelt Rd
Glen Ellyn, IL 60137-5927

Dear Ms. Hoit,

This letter is in response to the unresolved item involving gaseous effluent sampling resulting from a routine safety inspection conducted April 21-23, 1993 at our facility. The specific unresolved item is associated with the potential for release of radioactive vapor or gaseous effluent during the preparation of uranium electroplating solution in the fume hood.

To resolve this issue, an air sample collected on an activated carbon filter cartridge will be analyzed for uranium. The sampling will be performed the next time uranium solution is prepared. We expect this event to occur within the next six to eight weeks. Results of the sampling will be communicated to you. Please contact me if I can offer additional information.

Sincerely,

Susan McElrath
Susan McElrath
Health Physicist

9307190011 930713
PDR ADDCK 03014418
C PDR

JUN 21 1993