

LER

BOSTON EDISON COMPANY
PROMPT REPORTABLE OCCURRENCE
TELECOPY MESSAGE

TO: (215) 337-5324
Telephone Number

DATE/TIME: 9/18/81 /

TO: Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

FROM: Pilgrim Nuclear Power Sta.
RFD#1, Rocky Hill Road
Plymouth, MA 02360


Docket Number 50-293
License DPR-35

Assigned LER Number 81-G51/01X-0

Reported per T.S. Section 6.9.B.1-C

Event Description: On 9/17/81, at 2115, a 1" test connection on the RHR minimum flowline was found to be broken off. This constitutes a degradation of primary containment integrity. Repairs were made, tests conducted and at 0720 on 9/18/81, the system returned to service. The NRC was notified via ENS.

Cause and Corrective Action: The cause of this event has been determined to be fatigue due to vibration.



Facility Status:

100 % Thermal MW

- | | | | |
|---------------------|-------|-------------------|-------|
| c) Routine Startup | _____ | g) Shutdown | _____ |
| d) Routine Shutdown | _____ | h) Refueling | _____ |
| e) Steady State | X | i) Other | _____ |
| f) Load Changing | _____ | j) Not Applicable | _____ |

A written followup report will be sent within two weeks.

NRC Person Notified J.R. Johnson NRCRI Prepared by G.G. Whitney

Mail (2) copies to:

Director
Office of Management Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

IE29
51/0

cc: Standard LER Distribution

8110020328 810918
PDR ADOCK 05000293
S PDR