



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

March 24, 1982

Regional Administrator
Region III
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137



PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-306 License No. DPR-60

Inoperability of No. 22 Auxiliary Feedwater Pump

The Licensee Event Report for this occurrence is attached.

This event is reported in compliance with Technical Specification 6.7.B.2.(b), since it represents operation in a degraded mode permitted by a limiting condition for operation.

Dain M. Mayer

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMH/bp

cc NRC Document Control Desk (1)
NRC Resident Inspector
MPCA
Attn J W Ferman

8204020307 820324
PDR ADOCK 05000306
S PDR

IE 22
1/1

MAR 29 1982