



March 26, 1982

Log No. K82-550  
File: RR 2 (NP-32-82-02)

Docket No. 50-346  
License No. NPF-3

Mr. James G. Keppler  
Regional Administrator, Region III  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137



Dear Mr. Keppler:

Reportable Occurrence 82-012  
Davis-Besse Nuclear Power Station Unit 1  
Date of Occurrence: March 14, 1982

Enclosed are three copies of Licensee Event Report 82-012 with a supplemental information sheet which is being submitted in accordance with Technical Specification 6.9 to provide 14 day written notification of the subject occurrence.

Yours truly,

*Terry D. Murray*

Terry D. Murray  
Station Superintendent  
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Richard DeYoung, Director  
Office of Inspection and Enforcement  
Encl: 40 copies

Mr. Norman Haller, Director  
Office of Management and Program Analysis  
Encl: 3 copies  
2 copies telecopy

Mr. Luis Reyes  
NRC Resident Inspector  
Encl: 1 copy

MAR 31 1982

8204080501 820326  
PDR ADOCK 05000346  
S PDR

ION PLAZA 300 MADISON AVENUE TOLEDO, OHIO 43652

IE22  
5/1