

# Washington Public Power Supply System

Box 1223 Elma, Washington 98541 (206) 482-4428

Docket Numbers 50-508 and 50-509

April 1, 1982  
G03-82-320

U. S. Nuclear Regulatory Commission, Region V  
Office of Inspection and Enforcement  
1450 Maria Lane, Suite 260  
Walnut Creek, California 94596-5368

Attention: Mr. T. W. Bishop  
Chief, Reactor Construction Projects Branch


Subject: PROJECT NOS. 3 AND 5  
INTERIM REPORT OF POTENTIAL 10CFR50.55(e)  
RT INDICATIONS ON SAFETY INJECTION TANKS  
AND REACTOR PUMP SUPPORTS (D/N #023)

Reference: Letter, G03-82-085, dated January 27, 1982, R. S.  
Leddick to B. H. Faulkenberry, same subject.

The referenced letter forwarded an interim report of the subject condition and noted that the next interim report would be provided to your office by April 1, 1982.

Interpretation of radiographic indications found in three weld areas (two in Safety Injection Tank #1 and one in Tank #2) has not been resolved. In an effort to provide a resolution, Combustion Engineering (CE) has agreed to furnish documentation that will justify their interpretation. A final report for the subject condition will be forwarded to your office upon receipt and evaluation of CE's interpretation. It is anticipated that this action will be completed by May 1982. Accordingly, the final report will be submitted by May 31, 1982.

Should you have any questions or desire further information, please contact me directly.



R. S. Leddick, 760  
Program Director, WNP-3

DRC/tt

cc: J. Adams - NESCO  
D. Smithpeter - BPA  
Ebasco - New York  
WNP-3/5 Files - Richland