

Carolina Power & Light Company

April 15, 1982

CQAD 82-665

FILE: SHN-2/18 Item 71

Mr. James P. O'Reilly United States Nuclear Regulatory Commission Region II 10: Marietta St., N.W. Atlanta, Georgia

62 APR DI CS . 1 4

SHEARON HARRIS NUCLEAR POWER PLANT UNIT 1 DOCKET NO. 50-400 DEFICIENCIES IN WELDED STUDS ON EMBEDDED STRIP FLATES

Dear Mr. O'Reilly:

Attached is Addendum No. 1 to the final 10CFR50.55(e) report issued to the NRC on March 19, 1982, for the above subject deficiency. This addendum describes an additional occurrence and the associated required corrective action. Please attach this addendum to the March 19, 1982, final report.

If you have any questions regarding this matter, please contact me.

Very truly yours,

N. J. Chiangi-Manager Engineering & Construction Quality Assurance/Quality Control

TH:pfb

8204280302

Attachment

cc: Mr. H. R. Banks Mr. P Mr. D. L. Bensinger (HI/A-2D) Mr. L Mr. A. B. Cutter Mr. A Mr. C. R. Dietz Mr. M Dr. T. S. Elleman Mr. C Mr. G. L. Forehand (2) Mr. R Mr. T. L. Harrington Mr. S Mr. E. Harris Mr. R Mr. S. Hinnant File

Mr. P. W. Howe Mr. L. I. Loflin Mr. A. M. Lucas Mr. M. A. McDuffie Mr. C. H. Moseley, Jr. Mr. R. M. Parsons Mr. Sheldon D. Smith Mr. R. B. Starkey, Jr. File

411 Fayetteville Street . P. O. Box 1551 . Raleigh, N. C. 27602



SHEARON HARRIS NUCLEAR POWER PLANT

UNIT NO. 1

DEFICIENCIES IN WELDED STUDS ON EMBEDDED STRIP PLATES

ADDENDUM NO. 1 TO FINAL REPORT ISSUED MARCH 19, 1982

April 15, 1982

On April 5, 1982, N. J. Chiangi notified the NRC (Mr. C. Julian) that another DDR had been written identifying the same type problem reported in a final 10CFR50.55(e) report dated March 19, 1982. During the discussion, it was agreed that since this additional DDR (No. 862) dealt with the same type deficiency, material and corrective action, it was not necessary for CP&L to provide an additional report. CP&L has provided the same corrective action for DDR No. 862 as indicated in the final report dated March 19, 1982.