Georgia Power Company. 333 Piedmont Avenue Atlanta, Georgia 30308 Telephone 404 526-7020

Mailing Address Post Office Box 4545 Atlanta Georgia 30302

J. T. Beckham, Jr. Vice President and General Manager Nuclear Generation USNRO REGION I

82 APR 28 AID : 3"

Georgia Power

April 22, 1982

REFERENCE: RII: JPO 50-366 I&E Bulletin

80-13

U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II - Suite 3100 101 Marietta Street, NW Atlanta, Georgia 30303

ATTENTION: Mr. James P. O'Reilly

GENTLEMEN:

Pursuant to the requirements of NRC I&E Bulletin 80-13, "Cracking In Core Spray Spargers," please be advised that a visual examination was performed on the Hatch Unit 2 Core Spray spargers and associated piping during the maintenance/refueling outage currently in progress. The results were satisfactory and are as follows:

Using remote underwater television cameras (with the required viewing in situ of 0.00l in. diameter fine wires), no cracking of the Core Spray spargers or section of piping between the inlet nozzle and the vessel shroud was detected.

If you have any questions in this regard, please contact this office.

Sincerely yours,

J. T. Beckham, Jr.

JAE/mb

xc: H. C. Nix, Jr.
R. F. Rogers, III
NRC Office of Inspection and Enforcement, Division of Reactor Operations Inspection