

CONTROL BLOCK: _____

REPORT SOURCE: L 6 0 5 0 0 0 2 1 9 7 1 0 0 5 8 1 0 1 1 0 3 8 1 9

DOCKET NUMBER: 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DATE: 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

REPORT DATE: 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

On October 5, 1981 during a diesel surveillance test, the diesel failed to automatically increase load above 2400 KW. The diesel governor was replaced and the diesel was available for required demand. Due to the reactor being shutdown and vented, the safety significance of this event is considered minimal.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE														
E	E	E		F		I	N	S	T	R	U	C		Z														
9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24													
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER		
8	1	0	4	7	0	3	L	0	0	0	0	Y	N	A	W	2	9	0	22	23	24	25	26	27	28	29	30	31
32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60

0	The cause of the incident was attributed to operational deterioration of
1	the governor. The governor was replaced.

FACILITY STATUS				% POWER				OTHER STATUS				METHOD OF DISCOVERY				DISCOVERY DESCRIPTION			
5	H	20		0	0	0	21	NA				B	31	Surveillance test					
ACTIVITY CONTENT				AMOUNT OF ACTIVITY				LOCATION OF RELEASE											
6	Z	33		Z	34	NA				NA									
PERSONNEL EXPOSURES				DESCRIPTION															
7	0	0	0	37	Z	38	NA												
PERSONNEL INJURIES				DESCRIPTION															
8	0	0	0	40	NA														
LOSS OF OR DAMAGE TO																			
8205060005 B11103				NA															
PDR ADOCK 05000219																			
S PDR																			

8205060005 811103
PDR ADOCK 05000219
S PDR

PUBLICITY
 ISSUED DESCRIPTION (1r)
 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20
 Weekly News Release
 F. X. Sullivan
 609-693-6037
 NRC USE ONLY