October 26, 1981

Dockets: 50-498 50-499

> Houston Lighting & Power Company ATTN: Mr. G. W. Oprea, Jr. Executive Vice President Post Office Box 1700 Houston, Texas 77001

Gentlemen:

Thank you for your letter of September 8, 1981, submitting your "Final Report Concerning Beam to Column Connection Design in the Reactor Containment Building." From our review of the submitted report, we find that you have not provided sufficient information to permit analysis and evaluation of the corrective action as required by 10 CFR Part 50.55(3). Specifically, since the finalization of specific design loads, the completion of the reanalysis, and the completion of the redesign and modification efforts have not been completed, your report lacks finality, in that it does not include the results of the as yet to be completed actions. This lack of detail is brought to light in the following example. You state that since the internal steel columns were designed initially to carry only vertical and local eccentric loads, the horizontal seismic loads will be transferred to the Secondardy Shield wall and the concrete floors. It is not clear whether the design of the Secondardy Shield wall or the floors will be affected by the imposition of the additional loads. The same question arises from the proposed application of the Reactor Containment Fan Cooler Duct Design Pressure Load to the Secondary Shield wall.

Your final report, in addition to addressing the proposed modifications, should state the scope of the design error, the design inputs which have finally been considered and the resultant stresses and safety margins which have been assured. Specific design calculations and modification details should remain available for review by this office during a follow-up inspection.

Sincerely,

"Original Signed by

W. C. Seidle, Chief Engineering Inspection Branch JE27

8205180653

| OFFICE | EMS EMS 64/1 | PS-3 wer | RPB ア ^ノ | EIB | IES | DD-RHV |
|--------|-----------------------|------------|--------------------|----------|-------------------|----------------------|
| | JITapia/nh REHall | WACrossman | GLMadsen | WCSeidle | JEGagliard | DTCollins |
| | 10/5/81 10/6/81 | T0/4/81 | 10/6 /81 | 10/1/81 | 10/20/81 | 1020/81 |
| | 318 I10 80) NRCM 0240 | OFFICIAL | RECORD C | OPY | ***************** | * USGPO 1980-329-824 |

Houston Lighting and Power Company

10.00

bcc to DMB for dist.

| BC | NRR/DHFS |
|----------|-------------|
| PM | NRR/OLB |
| AEOD | RAD ASMT BE |
| ELD | RESEARCH |
| IE FILE | LPDR |
| IE/RPRIB | NSIC |
| NRC PDR | |

bcc dist. by RIV

-2-

Texas Dept. of Health Resources RRI-South Texas

| OFFICE | | | | |
|----------|-------------------------|----------|----------------------|----------------------|
| SURNAME | | | manna minima | |
| DATE | | | annonanna manannanna | |
| NRC FORM | 4 318 (10/80) NRCM 0240 | OFFICIAL | RECORD COPY | + USGPO 1980-329-824 |