CP&L

Carolina Power & Light Company

ATLANTA, GEORGION

April 30, 1982

82 MAY 6 A 9: 38

FILE: SH N-2/18 ITEM 77 CQAD 82-773

Mr. James P. O'Reilly United States Nuclear Regulatory Commission Region II 101 Marietta Street, Northwest Atlanta, Georgia 30303

SHEARON HARRIS NUCLEAR POWER PLANT UNIT 1

DOCKET NO. 50-400
WELDING DEFICIENCIES ON SEISMIC I HANGERS AND STRUCTURAL STEEL

Dear Mr. O'Reilly:

On April 2, 1982, the NRC (Mr. C. Julian) was notified by Carolina Power & Light Company (Mr. L. E. Jones) of an item considered potentially reportable per the provisions of 10CFR50.55(e) and 10CFR21. The NRC was informed that certain Seismic I pipe hangers and structural steel supplied by Peden Steel, Raleigh, North Carolina, were found to have welding deficiencies.

The intent of this letter is to inform you that Carolina Power & Light Company has not been able to complete its evaluation concerning this matter since reinspections have not been completed to determine the scope of the problem.

Due to the amount of reinspection involved, it is now anticipated that the completion of the reportability evaluation will be accomplished by December 15, 1982, at which time, the NRC will be informed of the results. Completion of corrective action will depend on the results of the evaluations and extent of corrective action required. Once the item is deemed reportable, the NRC will be so notified, and the projected date of completion of corrective action and final report provided through submittal of an interim letter.

8205210306 820430 PDR ADDCK 05000400 S PDR

TE21

Mr. James P. O'Reilly - 2 -April 30, 1982 Thank you for your cooperation in this matter. Yours very truly, N. J. Chiangi - Manager Engineering & Construction Quality Assurance/Quality Control NJC/gea (206) cc: Mr. G. Maxwell Mr. V. Stello (2)