

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 C O F S V 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 2 0 4 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 2 6 7 7 0 4 1 2 8 2 8 0 5 1 2 8 2 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During a planned reduction in reactor power, the separation in axial positions of two
0 3 partially inserted control rod-groups fell slightly below the LCO limit of 10 feet.
0 4 This constitutes operation in a degraded mode of Fort St. Vrain Technical Specifi-
0 5 cation LCO 4.1.4 and is reportable per Technical Specification AC 7.5.2(b)2 and
0 6 7.5.2(b)3. No accompanying circumstances. No effect upon public health or safety.
0 7 No similar reports.

0 8

0 9 SYSTEM CODE R B 11 CAUSE CODE A 12 CAUSE SUBCODE A 13 COMPONENT CODE C O N R O D 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 18 19 20
17 LER/RO REPORT NUMBER 18 12 21 22 23 24 26 27 28 29 30 31 32 REVISION NO. 0
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED NPED-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
X 18 H 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 N 25 G 0 5 3 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Control rods were repositioned in accordance with established procedures. Operator
1 1 training to include instruction in the requirements and significance of LCO 4.1.4.
1 2 No further corrective action anticipated or required.
1 3
1 4

1 5 FACILITY STATUS E 28 % POWER 0 1 0 29 N/A OTHER STATUS 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION 32 Operator Observation
7 8 9 10 12 13 44 45 46 80

1 6 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 34 N/A AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
7 8 9 10 11 44 45 80

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
0 0 0 0 37 38 N/A
7 8 9 11 12 13 80

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION 41
0 0 0 0 40 N/A
7 8 9 11 12 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
Z 42 N/A
7 8 9 10 80

2 0 PUBLICATION ISSUED DESCRIPTION N/A 44 3205240114 820512 PDR ADOCK 05000267 PDR
7 8 9 10 80

NAME OF PREPARER

Charles Fuller

PHONE: (303) 785-2224

NRC USE ONLY