July 15, 1981

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

NESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE REPORT SQR0-50-327/81071

The enclosed report provides details concerning the inoperability of the "B" train main control room emergency ventilation system. This event resulted in entering limiting condition for operation 3.7.7.1 and is reported under Sequoyah unit 1 Technical Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

Director of Nuclear Power

Enclosure (3) cc (Enclosure): Director (3) Office of Management Information and Program Control U.S. Nuclear Regulatory Commission Washington, DC 20555

Director (40) Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555

Mr. Bill Lavallee Nuclear Safety Analysis Center Palo Alto, California 943C3

NRC Inspector, Sequoyah

BACKEIT

8205240428 810715 PDR ADOCK 05000327 S PDR