

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

April 20, 1982

32 APR 23 48:50

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET  
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE  
REPORT BFRO-50-259/82023

The enclosed report provides details concerning "A" recirculation pump  
tripping because of operation of the generator stator temperature relay.  
This report is submitted in accordance with Browns Ferry unit 1 Technical  
Specification 6.7.2.b.2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*J. A. Green*

M. J. Green  
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Records Center  
Institute of Nuclear Power Operations  
1820 Water Place  
Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

8206010598 S

An Equal Opportunity Employer

OFFICIAL COPY  
IE 22

5/1/1