



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

May 20, 1982

Regional Administrator
Region III
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Failure of Drywell Vent Isolation Valves - Update Report

The updated License Event Report for this occurrence is attached. Our original April 23, 1982 report contained an error in the serial number given for the defective solenoid valves.

David Musolf for

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/bd

cc: NRC Document Control Desk (1)
NRC Resident Inspector
MPCA
Attn: J W Ferman

Attachment