

mm

RECEIVED
IRO
MAY 26 AM 10:58
REGION V III

Washington Public Power Supply System

Box 1223 Elma, Washington 98541 (206) 482-4428

Docket Numbers 50-508 and 50-509

May 21, 1982
G03-82-525

U. S. Nuclear Regulatory Commission, Region V
Office of Inspection and Enforcement
1450 Maria Lane, Suite 260
Walnut Creek, California 94596-5368

Attention: Mr. B. H. Faulkenberry
Acting Chief, Reactor Construction Projects Branch


Subject: PROJECT NOS. 3 AND 5
REPORTABLE 10CFR50.55(e) DEFICIENCY
STRUCTURAL STEEL CONNECTIONS - UNITS 3 AND 5 (D/N #019)

- References:
1. G03-81-2756, dated November 17, 1981, Mr. R. S. Leddick to Mr. B. H. Faulkenberry, Final Report of Potential 10CFR50.55(e), Structural Steel Connections - Unit No. 5 (D/N #019).
 2. G03-82-101, dated January 29, 1982, Mr. R. S. Leddick to Mr. B. H. Faulkenberry, Final Report of Potential 10CFR50.55(e), Structural Steel Connections - Unit No. 3 (D/N #019 and 021).
 3. NRC Letter, dated April 21, 1982, Docket No. 50-508/509, Mr. T. W. Bishop to Mr. R. S. Leddick, same subject.

References 1 and 2 provided your office with the final reports for the subject 10CFR50.55(e) condition. Upon review of the reports, your staff determined that additional information was required to complete the analysis and evaluation of the deficiencies and corrective action. Accordingly, Reference 3 outlined NRC questions that had arisen and directed the Supply System to provide a response.

The Supply System has received the AE's response to the NRC questions; however, prior to forwarding it to your office, it has been determined that further analysis and clarification is required. Consequently, the requested information will be provided by July 23, 1982.

Should you have any questions or desire further information, please contact me directly.


R. S. Leddick, 760
Program Director, WNP-3

DRC/tt

cc: J. Adams - NESCO
D. Smithpeter - BPA
Ebasco - New York
WNP-3,5 Files - Richland