6.11;

1.00	Elochoci Evisii neroni
***	CONTROL BLOCK: THE ALL REQUIRED INFORMATION
0 1	T N S N P 1 3 0 0 - 10 0 0 0 0 - 10 0 3 4 1 1 1 1 1 4 5 TO CAT 50 57 CAT 50
CON'T	PREPORT L 6 0 5 0 0 0 3 2 7 7 0 5 0 2 8 2 8 0 5 2 8 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 Ut.it 1 in mode 1 at 100% reactor power. At 0430 hours, steam generator blowdown
	containment isolation valve 1-FCV-1-25 would not reopen after blowdown was isolated.
0 3	The valve was declared inoperable. This event required entry into LCO 3.6.3.1.
0 4	
0 5	There was no effect on public health or safety. Previous occurrences - one.
0 6	(Reference SQRO-50-328/82009.)
0 7	
0 8	
0 9	CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	LER/RO EVENT YEAR REPORT NO. 17) REPORT NO. REPORT NO. 17) REPORT NO. 18 2
	found ruptured and the cause has been determined as normal wear (Masoneilan Model
1 2	number 38-70521-5). The diaphragm was replaced and the valve was returned to
1 3 R*	service at 2015 hours on 05/02/82. No additional action is planned at this time.
Jan E	ACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION (32)
1 5	E 28 1 0 0 29 NA A 31 Operation of valve
16	CIVITY CONTENT CLEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 NA NA 80
17	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 O O O D S S S S S S S S S S S S S S S S
18	FERSONNEL INJURIES 13 8206070162 820528 PDR ADOCK 05000327
1 4	0 0 0 40 NA S PDR 9 11 12 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION (43)
119	Z j (42) NA
7 °	PUBLICITY SSUED DESCRIPTION 45 NAC USE ONLY
/ 8	9 10

Name of Preparer A. M. Carver /M. R. Harding Phone (615) 751-0349