

LICENSEE EVENT REPORT

CONTROL BLOCK.

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[illegible]

CON'T

REPORT SOURCE L 6 0 5 0 0 0 3 1 5 7 0 2 1 5 8 1 3 0 6 0 3 8 2 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 DURING NORMAL OPERATIONS, THE WEST MOTOR DRIVEN AUXILAIRY FEED PUMP WAS REMOVED
0 3 FROM SERVICE TO REPAIR THE EMERGENCY LEAKOFF LINE CHECK VALVE, FW-160. THIS
0 4 CONSTITUTED AN INOPERABLE PUMP PER T.S. 3.7.1.2. THE VALVE HAD LEAKED BY
0 5 DURING A TEST OF THE EAST PUMP ON 2/14/81. THE EAST PUMP REMAINED IN
0 6 SERVICE AND THE ACTION REQUIREMENTS WERE MET. PUBLIC HEALTH AND SAFETY
0 7 WERE NOT AFFECTED. A SIMILAR OCCURRENCE WAS REPORTED AS RO 81-002/03L-0
0 8 FOR DOCKET NO. 050-316.

SYSTEM CODE C H 11		CAUSE CODE E 12		CAUSE SUBCODE B 13		COMPONENT CODE V A L V E X 14		COMP SUBCODE C 15		VALVE SUBCODE A 16							
EVENT YEAR 8 1		SEQUENTIAL REPORT NO. 0 0 2		OCCURRENCE CODE 0 3		REPORT TYPE X		REVISION NO. 1									
ACTION TAKEN D 18		FUTURE ACTION F 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED N 23		NPRO-4 FORM SUB. N 24		PRIME COMP. SUPPLIER A 25		COMPONENT MANUFACTURER C 6 3 1 26	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 3 A SMALL AMOUNT OF DIRT WAS FOUND IN THE VALVE WHICH APPARENTLY CAUSED THE

1 1 VALVE TO STICK. THE VALVE WAS CLEANED AND RETURNED TO SERVICE. AN OPERATIONAL

1 2 TEST WAS PERFORMED WITH NO FURTHER LEAKAGE DETECTED. A MODIFICATION HAS BEEN

1 3 INITIATED FOR REPLACEMENT OF EXISTING CHECK VALVES WITH HORIZONTAL SWING CHECK

1 4 VALVES AND ADDITION OF RELIEF VALVES IN THE PUMP SUCTION LINES.

FACILITY STATUS (1) E (29) % POWER (1) 1 (2) 0 (3) 0 (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (31) B DISCOVERY DESCRIPTION (32) OPERATOR OBSERVATION

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION				
1	7	0	0	0	37	Z	38	NA	39

		7	8	9	10	11	12	13		
		PERSONNEL INJURIES								80
		NUMBER DESCRIPTION (41)								
1	2	0	0	0	(AD)	NA				

LOGS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION NA

1	9
---	---

Z (42)

7 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

PUBLICITY (45)
ISSUED (14) DESCRIPTION (45)
NA
8206100254 820603
PDR ADDCK 05000315
S PDR
NRC USE ONLY

NAME OF PREPARER DAVID G. WIZNER

PHONE 616-465-5901