

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
M I D C C 2 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 4 5
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
CON'T
REPORT SOURCE L 6 0 5 0 0 0 3 1 6 7 1 0 2 3 8 1 8 0 6 0 3 8 2 9
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
0 2 DURING A PLANT HEATUP AT THE POINT OF MODE CHANGE FROM 4 TO 3, THE RCS LEAK
0 3 RATE WAS ESTIMATED TO BE IN EXCESS OF THE LIMITS OF T.S. 3.4.6.2.D. THE LEAKAGE
0 4 WAS IDENTIFIED AS BEING THROUGH SAFETY VALVE SV-51 ON THE NORMAL LETDOWN LINE.
0 5 THE LEAKAGE WAS CONFINED TO THE PRESSURIZER RELIEF TANK. HEALTH AND SAFETY
0 6 WERE NOT AFFECTED.
0 7
0 8

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
S F 11 E 12 B 13 V A L V E X 14 J 15 B 16
LER NO. REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
8 1 0 5 8 0 3 X 1
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
C 18 Z 19 C 20 Z 21 0 0 0 0 N 22 Y 24 N 25 C 7 1 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 3 THE CROSBY 2" X 3" STYLE JB-25-3 VALVE WAS FOUND TO BE LIFTING AT 230 PSIG RATHER
1 1 THAN ITS 600 PSIG SETPOINT. THE LOW SETPOINT WAS DUE TO EXCESSIVE SEAT LEAKAGE.
1 2 THE VALVE WAS REPLACED WITH A NEW VALVE. INSPECTION OF THE FAILED VALVE DETERMINED
1 3 THAT VALVE SEAT LEAKAGE ALLOWED THE SYSTEM PRESSURE TO ACT ON A LARGER SURFACE
1 1 AREA WHICH EFFECTIVELY LOWERED ITS SETPOINT.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
C 28 0 0 0 29 NA A 31 OPERATOR OBSERVATION 32
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z 33 Z 34 NA 35 NA 36
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
0 0 0 37 Z 38 NA 39
PERSONNEL INJURIES NUMBER DESCRIPTION
0 0 0 40 NA 41
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
Z 42 NA 43
PUBLICATION ISSUED DESCRIPTION
N 44 NA 45
8206100287 820603
PDR ADDOCK 05000316
S PDR
NRC USE ONLY
68 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NAME OF PREPARER DAVID G. WIZNER

PHONE 616-465-5901