1. LIC	ENSEE		1. REGIONAL OFFICE		
W	eterans Administration H Wilshire and Swwtelle Bou Los Angeles, California	levards	Operations U. S. Atomic P. O. Box 151	Energy Commission 5 ifornia 94701	
3. 00	CKET NUMBER(S)	4. LICENSE NUMBER(S	5)	5. DATE OF INSPECTION	
	SPECTION FINDINGS	04-00181-04		SEPT. 28, 1973	
The i	ospection was an examination of the act	inditions of your license. The	inspection consisted of sel	radiation safety and to compliance with the	
X.	No items of noncompliance or un	safe conditions were foun	d.		
The	following items of noncompliance r	elated to records, signs, a	nd labels were found:		
	A. Rooms or areas were not prope	erly posted to indicate the	presence of a RADIAT	TION AREA. 10 CFR 20.203(b) or 34.42	
	B. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42				
	C. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)				
	D. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)				
	E. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)				
	F. A current copy of 10 CFR 20, made available, 10 CFR 20,206	F. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)			
	G. Form AEC-3 was not properly	posted. 10 CFR 20.206(c	(:)		
	H. Records of the radiation expos	Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)			
	I. Records of surveys or disposals	were not properly maint	ained. 10 CFR 20.401(b) or 34.43(d)	
	J. Records of receipt, transfer, dis 10 CFR 30.51, 40.61 or 70.51	sposal, export or inventor	ry of licensed material v	vere not properly maintained.	
	K. Records of leak tests were not	maintained as prescribed	in your license, or 10 C	FR 34.25(c)	
	L. Records of inventories were not maintained. 10 CFR 34.26				
	M. Utilization logs were not maintained. 10 CFR 34.27				
	N. Records of radiation survey ins	strument calibration were	not maintained. 10 CF	R 34.24	
	O. Records of teletherapy electrical interlock tests were not maintained as prescribed in your license.				
	P. Other		MA		
þij			HIMP		
no	ne AEC Compliance Inspector has ex oncompliance will be corrected within		the items of noncompl		
PDR NEL	4150427 820216 FOIA SON82-11 PDP				
	(Date)		(Licensee Representa	tive - Title or Position)	