## LICENSEE EVENT REPORT

	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	CASOSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
0 1 3	REPORT L 6 0 5 0 0 0 3 6 1 7 0 3 0 8 8 2 8 0 4 0 7 8 2 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  On March 8, 1982 at 1205, with core alterations in progress, operations
0 3	personnel discovered that Containment Purge Isolation System (CPIS)
0 4	operability had not been demonstrated within 7 days as required by
0 5	Technical Specification 4.99. Core alterations were halted for
0 6	approximately two hours while CPIS operability was demonstrated. There
0 7	was no effect on public health and safety as a result of this incident.
0 8	
7 8	SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
	LER/RO EVENT YEAR SEQUENTIAL REPORT NO.  17 REPORT   8 2
10	CPIS testing was not conducted at the scheduled time as purge valves
11	were out of service to permit valve seat cleaning. Purge valves were
1 2	returned to service without verifying CPIS operability. Operating
113	personnel have been instructed to log all incomplete surveillance tests
114	and to identify the tests as prerequisite to returning equipment to service.
1 5 F <sub>5</sub>	B 28 0 0 0 0 29 NA B 31 Operator Observation 32
1 6 RE	LEASED OF RELEASE AMOUNT OF ACTIVITY (35)  NA LOCATION OF RELEASE (36)  NA N
17	NUMBER OF SCRIPTION (39)  NA  NA
	PERSONNEL INJURIES NUMBER O O O O O O O NA NA
	B204160295 B20407  TYPE DESCRIPTION PDR ADOCK 05000361  B DR ADOCK 05000361  PDR ADOCK 05000361
13 0	NAC USE ONLY
	NAME OF PREPARED H.B. Ray (714) 492-7700