

P. A. Morris, Assistant Director for
Reactors, Div. of Compliance, Eqs.

DEC 2 1960

Robert W. Kirkman, Director
Compliance Division, NYDO

THE WATERTOWN ARSENAL REACTOR

CMP:WRS

Leaks in swimming pool reactors seem to be almost standard. We understand that the final solution for many reactors has been pressure grouting. However, this is usually a fairly expensive process, so that everyone first attempts to do a patch-up job. This is exactly the stage that the Watertown Arsenal people are going through right now. So far, they have eliminated a large number of the bigger leaks, and in our opinion the remaining leaks are more of a nuisance problem than a health hazard.

Enclosure:
2 cys Rpt.

8204210551 811005
PDR FOIA
KABAT-Z81-311 PDR

Compliance

Sears:pm Kirkman
12/1/60