D. L. Caphton, Section Leader 2 RO&NS Branch

AMMRC DN 50-47 LIC R-65 INSPECTION 50-47/75-01 INSPECTOR'S EVALUATION

- On November 25, 1975, I conducted an inspection of the licensed AMMRC reactor facility at Watertown, Massachusetts which has been in "Standby" status since 1970. Findings are included in the Inspection Report.
- There are no current plans to change the facility status due primarily to a lack of funding for dismantling. One unsolicited proposal to dismantle, set the price at approximately \$1x106.
- 3. The principals responsible for administration of the license are assigned primary functions in other areas and, as a result, appear to devote minimal attention to the reactor. Surveillance activities have been delegated to the Post Engineer and are receiving little supervisory attention. The RSC had not met for 18 months and has conducted no Technical Specification required audits.
- 4. Due primarily to the above indications of lack of attention and, in keeping with a previous evaluation made by the Project Inspector in July 1974, I plan to continue at least annual inspections for this facility.

L. J. Norrholm Reactor Inspector