LICENSEE EVENT REPORT

LER 81-26/3L

LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
V T V Y S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 57 CAT 58
REPORT L 6 0 5 0 0 0 2 7 1 7 1 0 0 5 8 1 8 1 0 3 8 1 9
During the weekly review of surveillance testing data, it was discovered that the
maximum monthly interval was exceeded by four days for the functional test of the
ATWS/RPT System required by T. S. 4.2.1. Since the test was immediately and
successfully performed there were no consequences to the health and safety of the
public. The only similar occurrence reported to the commission in the last five
years was RO 80-34/3L.
80
SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
SEQUENTIAL OCCURRENCE REPORT NO. 17 REPORT NO. 0 2 6 0 3 L.
ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER X 18 H 19 Z 20 Z 21 0 0 0 N 23 N 24 N 25 Z 9 9 9 2 33 34 34 42 43 43 44 47 47 47 47 47
The test was not done because of an oversight in scheduling. The test was immediate!
ly and successfully completed and applicable personnel have been reinstructed in the
implementation of the surveillance testing program.
FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 [E 28 0 9 6 29 NA B 31 Document Review]
2 13 44 45 46 ACTIVITY CONTENT 12 13 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 NA NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA NA NA 80 NA
PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA NA
SO LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA
9 10 PUBLICITY (45) NRC USE ONLY
NA NA SECRIPTION SECRI
30076 811103 Warren P. Murphy PHONE: (802) 257-7711
2