

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

02 MAR 29 P 1: 5 March 24, 1982



U.S. Nuclear Regulatory Commission
Region II
ATTN: James P. O'Reilly, Regional Administrator
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

OFFICE OF INSPECTION AND ENFORCEMENT BULLETIN 78-01 - RII:JPO 50-259, -260, -296, -327, -328, -390, -391, -438, -439, -518, -519, -520, -521, -553, -554, -566, -567 - FLAMMABLE CONTACT ARM RETAINERS IN GE CR120A RELAYS - BROWNS FERRY NUCLEAR PLANT

Please reference R. C. Lewis' letter dated March 10, 1981, transmitting NRC Inspection Report 50-259/80-47, -260/80-37, and -296/80-41 for Browns Ferry Nuclear Plant, and your letter dated January 16, 1978, transmitting IE Bulletin 78-01. Our initial response to the subject bulletin was submitted to your office on February 13, 1978. This letter constitutes our supplemental response to the subject bulletin.

Additional research has been performed to determine locations of GE CR120A relays which might have been overlooked in our initial search. Drawings of various systems were reviewed and possible additional CR120A relays were identified. These relays have been inspected and all contact arm retainers have been changed out and marked in accordance with revised Electrical Maintenance Instruction 53. This completes the action required in open item 259/80-47-02.

If you have any questions, please call Jim Domer at FTS 858-2725.

To the best of my knowledge, I declare the statements contained herein are complete and true.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

A handwritten signature in cursive script, appearing to read "L. M. Mills".

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Director of Reactor Operations Inspection
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. R. C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8204230464

Q