




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P O BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345



June 3, 1982

G. D. McLENDON
Senior Vice President

W3K-82-0320
Q-3-A35.07
Q-3-A35.07.40
Q-3-A35.07.47

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Potential Reportable Incident No. 52
Significant Construction Deficiencies No.'s 40 and 47

Reference: Telecon - R. G. Bennett (LP&L) to L. Martin (NRC) on 6/1/82

Dear Mr. Collins:

The final reports for the subject Significant Construction Deficiencies and the Potential Reportable Incident will not be submitted as previously committed. The following information explains the status of each item:

SCD #40 - ITE Could Starter Coil Failure in Containment Cooling Fans

Due to the limited amount of rework remaining to complete the corrective action, a final report will be submitted by June 15, 1982.

SCD #47 - General Electric AKR 30/50 Circuit Breakers Closing Spring Screw

Due to the amount of work necessary to complete the corrective action, the final report will not be submitted until June 30, 1982.

PRI #52 - Reactor Coolant Pump Supports - A490 Bolts

As the evaluation is complete and the report is being finalized, the final report will be submitted by June 7, 1982.

Very truly yours,

GDMcL/LLB/grf

8206110254 820603
PDR ADOCK 03000382
S PDR

IE-27

Mr. John T. Collins
Page 2

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555