



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76011

Enclosure 8

February 19, 1982

Docket: 99900345/82-01

Hayward Tyler Pump Company
80 Industrial Parkway
P. O. Box 492
Burlington, Vermont 05402

Gentlemen:

This refers to the investigation conducted by Mr. R. K. Herr, Mr. D. D. Driskill, and Mr. L. E. Ellershaw of our staff on January 4-29, 1982, at your facility in Burlington, Vermont, concerning allegations dealing with upper management's failure to support and/or enforce the QA program. The investigation and our findings are discussed in the enclosed investigation report.

During the course of this investigation, the NRC, Region IV office also conducted a concurrent inspection of your facility. This inspection report, identified as 99900345/82-02, contains 12 identified nonconformances. To preclude duplication, nonconformances will not be addressed within this report.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC Public Document Room unless you notify this office, by telephone, within 10 days of the date of this letter and submit written application to withhold information contained therein within 30 days of the date of this letter. Such application must be consistent with the requirements of 2.790(b)(1).

Should you have any questions concerning this investigation, we will be pleased to discuss them with you.

Sincerely,

Karl V. Seyfrit, Acting Director
Enforcement and Investigation Staff

Enclosure:
Appendix - Investigation Report
99900345/82-01

bcc to DMB (IE01):

BC
PM
AEOD
ELD
IE FILE
IE/RPRIB
NRR/DHFS
NRR/OLB
RAD ASMT BR
RESEARCH
LPDR
NRC PDR
NSIC
NTIS

bcc distrib. by RIV:

D. Herr
D. Driskill
L. Ellershaw
I. Barnes
J. Gagliardo
J. Collins
K. Seyfrit
Info System
RIV File