



Commonwealth Edison

Dresden Nuclear Power Station

R.R. #1

Morris, Illinois 60450

Telephone 815/942-2920

June 3, 1982

DJS Ltr. #82-629

James G. Keppler, Regional Administrator
Directorate of Regulatory Operations - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellen, IL 60137

Updated report on Reportable Occurrence 82-11/03X-1, Docket #050-249 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2(d), abnormal degradation of systems other than those specified in item B.1.e above designed to contain radioactive material resulting from fission process. This revised report indicates the remedial action taken to replace the defective valve with a like for like check valve made by the Mission Company. It also corrects inadvertent reporting in the original LER that the defective valve was made by the Crane Company.

D. J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/nh

Enclosure

cc/ Director of Inspection and Enforcement
Director of Management Information and Program Control
U.S. NRC, Document Management Branch
File/NRC

8206210085 820603
PDR ADDCK 05000249
S PDR

JUN 16 1982