




**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

June 17, 1982

G. D. McLENDON  
Senior Vice President  
W3K82-0355  
Q-3-A35.07.26

Mr. John T. Collins, Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 26  
"Feedwater Isolation Valves - Temperature Maintenance of Actuators"  
Third Interim Report

Reference: 1) LP&L Letter W3K81-0363 to NRC dated October 1, 1981  
2) Telecon - L. Martin (NRC) to L. Bass (LP&L) on June 16, 1982

Dear Mr. Collins:

The physical work on the corrective action for the protection of the actuators is complete. However, NCR W3-3872 and NCR W3-3483 resulted from work accomplished as part of the corrective action. The conditions addressed on the two nonconformance reports must be corrected prior to reporting the final corrective action complete. LP&L respectfully requests an extension on SCD No. 26 until July 13, 1982 at which time a final report will be submitted.

Very truly yours,

GDMcL/LLB/ncd

- cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555
- 2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

IE-27