

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

June 23, 1982

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

82 JUN 28 A 8:30
TELEPHONE AREA 704
3-4083
USNRC REGION 2
ATLANTA, GEORGIA

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/82-38. This report concerns T.S.4.5.1.2, "Each Upper Head Injection Accumulator System shall be demonstrated operable:...c. At least once per 18 months by: 1. Verifying that each accumulator isolation valve closes automatically when the water level in the instrument calibration line is $73.3 + 0.25$ inches above the bottom inside edge of the water-filled accumulator...". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

William O. Parker, Jr.
William O. Parker, Jr.

PBN/jfw
Attachment

cc: Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. P. R. Bemis
Senior Resident Inspector - NRC
McGuire Nuclear Station

OFFICIAL COPY

TE 22