

Docket No. 50-362

50.55(e) Report

Southern California Edison Company

P. O. BOX 800
2244 WALNUT GROVE AVENUE
ROSEMEAD, CALIFORNIA 91770

J. M. CURRAN
MANAGER, QUALITY ASSURANCE

June 23, 1982

Mr. R. H. Engelken,
Regional Administrator
U. S. Nuclear Regulatory Commission
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94506

Dear Mr. Engelken:


Subject: Docket No. 50-362
San Onofre Nuclear Generating Station, Unit 3

This letter confirms verbal notification on June 21, 1982 of a condition discovered in construction which is considered reportable in accordance with 10CFR50.55(e).

This condition involves a design error in the wiring between the control rod drive cabinets and the core protection calculator. The design was performed by Combustion Engineering of Windsor, Connecticut.

We are performing an evaluation of this condition and will submit an appropriate report in accordance with 10CFR50.55(e)(3). If you have any questions or require additional information, please let me know.

Very truly yours,



cc: A. E. Chaffee (NRC, San Onofre Units 2 & 3)
Dr. L. T. Papay

8207070147 820623
PDR ADOCK 05000362
S PDR

1E27

RECEIVED
MRC

SCE

1982 JUN 28 PM 1:22

REGION V

TELEPHONE
(213) 972-1695