




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345



July 15, 1982

G. D. McLENDON
Senior Vice President

W3K 82-0421
Q-3-A35.07.50

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

Subject: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 50
"Possible Malfunction in Agastat E7000 Series Time-Delay Relay"
Third Interim Report

Reference: LP&L Letter W3K 82-0271 to USNRC dated May 17, 1982

Dear Mr. Collins:

LP&L stated in the referenced letter that a final report would be submitted by July 15, 1982. Due to the unavailability of replacement parts, the corrective action has not been completed.

Replacement relays have been ordered by Ebasco and are expected on site by mid-October. A Final Report will be issued on this Significant Construction Deficiency by November 30, 1982.

If you have any questions, please advise.

Very truly yours,

G. D. McLendon

GDMcL/LLB/grf

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

FE 27