

APPENDIX  
NOTICE OF VIOLATION

Weyerhaeuser Company  
Valliant, Oklahoma

Docket: 030-12249  
License: 35-14074-02

During an NRC inspection conducted on June 19, 1990, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1990) (Enforcement Policy), the violation is listed below:

License Condition 16 of NRC Materials License No. 35-14074-02 states, in part, that the license is based on the licensee's statements and representations in an application dated March 23, 1982. Item 15 of the application states, in part, that sources are locked in a stored position before employees are authorized to enter vessels.

Contrary to the above, on April 23 and 24, 1990, six contractor employees entered a vessel in which the sources were not locked in a stored position.

This is a Severity Level IV violation. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, Weyerhaeuser Company is hereby required to submit to this office, within 30 days of the date of the letter transmitting this Notice, a written statement or explanation in reply, including for each violation: (1) the reason for the violation if admitted, (2) the corrective steps which have been taken and the results achieved, (3) the corrective steps which will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.

Dated at Arlington, Texas,  
this 26<sup>th</sup> day of June 1990