

Docket File



UNITED STATES
NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

August 26, 1993

Docket No. 52-003

MEMORANDUM FOR: R. W. Borchardt, Acting Director
Standardization Project Directorate
Associate Directorate for Advanced Reactors
and License Renewal, NRR

FROM: Frederick W. Hasselberg, Project Manager
Standardization Project Directorate
Associate Directorate for Advanced Reactors
and License Renewal, NRR

SUBJECT: NOTICE OF MEETING WITH WESTINGHOUSE TO DISCUSS LOW-PRESSURE
INTEGRAL TESTING OF THE AP600 DESIGN

DATE & TIME: September 20, 1993 (8:15 a.m. - 5 p.m.)

LOCATION: Oregon State University
LaSells Stewart Center
Agricultural Science Room
26th Street and Western Boulevard
Corvallis, Oregon 97330

PURPOSE: To obtain detailed information on the design and expected
operation of the low-pressure integral systems test facility
at Oregon State University and Westinghouse Electric Compa-
ny's plans for obtaining long-term cooling data from matrix
tests at the facility. Data from these tests will be used in
support of the Westinghouse AP600 design certification appli-
cation. A preliminary meeting agenda and directions to the
LaSells Stewart Center are enclosed.

NOTE: Proprietary features of the AP600 design will be discussed.

800010

9309090453 930826
PDR ADOCK 05200003
A PDR

NRC FILE CENTER COPY

DF03

August 26, 1993

PARTICIPANTS: * NRC WESTINGHOUSE ACRS DOE

R. Jones	B. McIntyre	I. Catton	J. Wheller
D. McPherson	L. Hochreiter	P. Davis	D. Harrison
M. Rubin	E. Piplica	T. Kress	
A. Levin	J. Butler	B. Lindblad	
L. Shotkin	L. Lau	E. Wilkins	
T. King	J. Hanson	V. J. Dhir	
D. Bessette	J. Reyes, OSU	W. Wulff	
F. Hasselberg	J. Groome, OSU	N. Zuber	
M. Ortiz, INEL		P. Boehnert	

(Original signed by)

Frederick W. Hasselberg, Project Manager
Standardization Project Directorate
Associate Directorate for Advanced Reactors
and License Renewal, NRR

Enclosures:
As stated

cc w/enclosures:
See next page

* Meetings between NRC technical staff and applicants or licensees are open for interested members of the public, petitioners, intervenors, or other parties to attend as observers pursuant to "Open Meeting Statement of NRC Staff Policy," 43 Federal Register 28058, 5/28/78. However, portions of this meeting may be closed to protect Westinghouse proprietary information. Members of the public who wish to attend should contact me at (301) 504-1141.

DISTRIBUTION:

Docket File	PDST R/F	TMurley/FMiraglia	DCrutchfield
PDR	WTravers	RBorchardt	NRR Mailroom
TEssig	FHasselberg	TKenyon	PShea
ACHaffee, EAB	TGody, EDO	JMoore, 15B18	ERossi
EJordan, MNBB3701	ACRS (11)	DMcPherson, 8E23	RJones, 8E23
MRubin, 8E23	ALevin, 8E23	LShotkin, NLN353	TKing, NLN368
DBessette, NLN353			

OFC	LA:PDST:ADAR	PM:PDST:ADAR	SC:PDST:ADAR
NAME	PShea <i>POS</i>	FHasselberg <i>[Signature]</i>	TEssig <i>[Signature]</i>
DATE	08/26/93	08/26/93	08/26/93

OFFICIAL RECORD COPY: OSUMEET.FH

cc: Mr. Nicholas J. Liparulo
Nuclear Safety and Regulatory Analysis
Nuclear and Advanced Technology Division
Westinghouse Electric Corporation
P.O. Box 355
Pittsburgh, Pennsylvania 15230

Mr. B. A. McIntyre
Advanced Plant Safety & Licensing
Westinghouse Electric Corporation
Energy Systems Business Unit
Box 355
Pittsburgh, Pennsylvania 15230

Mr. John C. Butler
Advanced Plant Safety & Licensing
Westinghouse Electric Corporation
Energy Systems Business Unit
Box 355
Pittsburgh, Pennsylvania 15230

Mr. M. D. Beaumont
Nuclear and Advanced Technology Division
Westinghouse Electric Corporation
One Montrose Metro
11921 Rockville Pike
Suite 350
Rockville, Maryland 20852

Mr. Sterling Franks
U.S. Department of Energy
NE-42
Washington, D.C. 20585

Mr. S. M. Modro
EG&G Idaho Inc.
Post Office Box 1625
Idaho Falls, Idaho 83415

Mr. Steve Goldberg
Budget Examiner
725 17th Street, N.W.
Room 8002
Washington, D.C. 20503

Mr. Frank A. Ross
U.S. Department of Energy, NE-42
Office of LWR Safety and Technology
19901 Germantown Road
Germantown, Maryland 20874

Westinghouse/NRC Meeting on
AP600 Low Pressure 1/4 Height Integral Systems Tests

September 20, 1993

Oregon State University
LaSells Stewart Center, Agricultural Science Room

- | | | | |
|----|---|----------|--------------|
| 1. | Welcome | OSU | 8:15 (:10) |
| 2. | Introduction/Background/Objectives | <u>W</u> | 8:25 (:15) |
| 3. | OSU Facility Design Update | <u>W</u> | 8:40 (:1:00) |
| | - Final Design | | |
| | - Break/Separator System | | |
| | <u>BREAK</u> | | 9:40 (:20) |
| 4. | OSU Instrumentation Design | <u>W</u> | 10:00 (2:00) |
| | - Walk Through Design and Logic | | |
| | <u>LUNCH</u> (Valley Football Center, \$9.00) | | 12:00 (1:30) |
| 5. | Facility Tour | OSU | 1:30 (1:00) |
| | <u>BREAK (return to meeting room)</u> | | 2:30 (:15) |
| 6. | OSU Scaling Analysis | OSU | 2:45 (1:30) |
| | - Brief Review of Chapters 1-4 | | |
| | - Depressurization Scaling, Chapter 5 | | |
| | - CMT, Accumulator, IRWST, Chapter 6 | | |
| | - Long Term Cooling, Chapter 7 | | |
| | - Scaling Distortions | | |
| 7. | Test Matrix | <u>W</u> | 4:15 (:30) |
| 8. | Schedule | <u>W</u> | 4:45 (:15) |
| 9. | Adjourn | | 5:00 |

Enclosure

DIRECTIONS FROM PORTLAND TO CORVALLIS

From the road leading away from Portland airport take Interstate Highway 205--head south on Interstate 205. Follow Interstate 205 until it meets Interstate 5. At that point continue south by going from Interstate 205 onto Interstate 5 at the sign marked south-Salem.

Follow Interstate 5 south to Exit #228 (Corvallis, Highway 34). Turn right off the freeway onto Highway 34 and follow Highway 34 west to Corvallis which is approximately 10 miles.

When you enter Corvallis you will cross a bridge over the Willamette River and will be on Harrison Blvd. To go to your motel, continue west on Harrison blvd. to 9th Street, turn right, and continue until you come to Garfield. Your motels will be located on the left.

To locate the LaSells Stewart Center, (from your motel) turn left on 9th Street and continue until you come to Harrison Street. Turn right on Harrison Street and continue until you come to 14th Street. Turn left on 14th Street. Keep going until you come to Western Blvd. Turn right on Western Blvd. and continue until you come to 26th Street. LaSells will be located on your right. To park, you need to park at Parker Stadium (across the street from LaSells Stewart Center).

DIRECTIONS FROM EUGENE TO CORVALLIS

From the road leading away from the Eugene airport take Highway 99--turn left on Highway 99. Follow Highway 99 through a little town called Junction City. At the north end of Junction City follow the signs leading to Monroe/Corvallis. There is a "Y" here at this intersection, you will take the left "Y." Follow Highway 99 north until you come to Corvallis.

You will come into downtown Corvallis. You will be on 3rd Street (a one way street). Continue until you come to Harrison Street. Turn left and continue until you reach 9th Street. To locate your motels, turn right on 9th Street and continue until you come to Garfield Street. Your motel will be located on the left.

To locate the LaSells Stewart Center, (from your motel) turn left on 9th Street and continue until you come to Harrison Street. Turn right on Harrison Street and continue until you come to 14th Street. Turn left on 14th Street. Keep going until you come to Western Blvd. Turn right on Western Blvd., continue until you come to 26th Street. LaSells will be located on your right. To park, you need to park at Parker Stadium (across the street from LaSells Stewart Center).

If you have any questions, please contact the AP600 office at 737-4677.