

U. S. NUCLEAR REGULATORY COMMISSION  
Region I

Report No. 50-271/82-12

Docket No. 50-271

License No. DPR-28 Priority -- Category C

Licensee: Vermont Yankee Nuclear Power Corporation

1671 Worcester Road

Framingham, Massachusetts 01701

Facility Name: Vermont Yankee

Investigation At: Vernon, Vermont

Investigation Conducted: June 6-10, 1982

Investigators: *Robert M. Gallo*  
for R. Keith Christopher, Investigator

7-15-82  
date signed

Reviewed By: *Robert M. Gallo*  
R. M. Gallo, Chief, Reactor Projects  
Section 1A, Projects Branch No. 1

date signed  
7/16/82  
date signed

Approved By: *R. T. Carlson*  
R. T. Carlson, Director  
Enforcement and Investigation Staff

7/20/82  
date signed

Investigation Summary:

Investigation on June 6-10, 1982 (Report No. 50-271/82-12)

The investigation was conducted separately but in conjunction with NRC Special Inspection 50-271/82-07 regarding the April 24, 1982 Loss of Feedwater Transient at the Vermont Yankee Nuclear Power Station. The investigation was conducted to determine if the licensee willfully, or with careless disregard withheld information regarding the event from the NRC duty officer while making a plant trip report and to examine the licensee's rationale for not declaring a site alert as specified by the Vermont Yankee Emergency Plan.

THE INFORMATION ON THIS PAGE IS DEEMED TO BE APPROPRIATE FOR PUBLIC DISCLOSURE PURSUANT TO 10 CFR 2.790

8207300168 820721  
PDR ADOCK 05000271  
Q PDR

THE REPORT DETAILS CONTAIN

(Exhibit 8)

S-F1-82- 75  
Copy 1 of 5 copies  
3 Pages